

## Warranty Vehicle Inquiry

Wed Nov 13 17:53:02 EST 2013

BZ94274 CONFIDENTIAL

THIS DOCUMENT IS NOT TO BE USED OR RELIED UPON FOR IMPORT OR EXPORT PURPOSES  
AND IS NOT TO BE DISTRIBUTED OR SHARED WITH THIRD PARTIES\*

\*EXCEPT FOR SPECIFIC INFORMATION THAT MAY BE REQUIRED BY LAW

DO NOT USE DAVIS AS THE SOLE INDICATOR FOR CALCULATING VEHICLES' DAYS OUT OF SERVICE.  
DAVIS IS A GUIDE ONLY AND DOES NOT INCLUDE EXACT NUMBERS AS CONFLICTS IN DAYS TO CLOSE A REPAIR ORDER MAY EXIST.

© 2013 BMW of North America, LLC

### Vehicle Data

**VIN:** WBSDE9349YBZ94274

**Chassis Number:** BZ94274

**Line Make:** 01 - BMW Car

**Model Year:** 2000

**AG Model Code/Desc:** DE93 - M5 US

**NA Model Code/Desc:** 0051 - M5

**Exterior Trim Code:** 354 - Titanium Silver Metallic

**Interior Color Code:** O6SS - SILVERSTONE NAPPA POINT LTHR

**MSRP:** \$72,545.00

**Davis #:** N/A

**TCU MIN:**

**Vehicle Production Date:** 1999/10

**Motor Type:** S62

**Platform/Engineering Series:** E39

**Wholesale Center ID/Loc:** 27600-01

**Wholesale Date:** 11/08/1999

**Retail Center ID/Loc:** 27600-01

**Retail Date:** 11/12/1999

**In-Service Date:** 11/12/1999

**See - Vehicle Comments**

### New Vehicle Warranty Info

**No Coverage As Of:** 11/12/2003

**Expiration Mileage:** 50,000

### Vehicle Comments

Add Date	Comment Status	Vehicle Comment
08/21/2007	Active	DINAN LG.A/F,PERF.SOFTWARE @ 83,302 MI.ANY FAILURES RELATED TO OR AS ACONSEQUENCE OF THIS OR ANY OTHER MODS ARE NOT COVERED BY THE ORIG.4/50,000 ORCPO WARRANTIES PER DOC.06/2007 NATIONAL VEHICLE FILE DATE POSTED 08/21/2007

NO OPEN CAMPAIGNS

**Option Information**

Code	Description	Code	Description
0320	Delete badge	0465	Split fold-down-rear seat
0769	100% OPTIONS	0971	5 SERIES MATS

**Customer Information**

Name (First/Last):

Address:

**Contract/Service Program Information(Administered by BMW NA)**

Type	Program Code/Desc	Contract Number/Status	Eff Date	Enroll Date	No Coverage As Of	Exp Age (Mth)	Exp Odometer (Miles)	Retail Center	Center Name	Vendor Code Used	Contract Holder (First/Last)
MP	000000115 - MP 36 MO/036K MLS	0000000 EXPIRED	11/12/1999	11/12/1999	11/12/2002	36	36,000	27600	Dreyer & Reinbold, Inc.	MP	
CPO	0000000005 - CPO 72 MO/100K MLS	0000000 EXPIRED	11/12/1999	01/15/2004	11/12/2005	72	100,000	27600	Dreyer & Reinbold, Inc.	UW	

**Repair History (Claims)**

Center ID	Location ID	Claim Number	Claim Date	Repair Order #	Repair Order Date	Repair Entry Date	Davis #	Mileage	Defect Code	Description
27600	01	375060	09/28/2006	275445	09/25/2006	09/28/2006	N/A	78,747	0012230200	SIB #12-11-06 ALPINA Z8 NOT AFFECTED RECALL 06E-A03 DME REPR
27600	01	375050	09/28/2006	275445	09/25/2006	09/28/2006	N/A	78,747	3452101500	DSC control module permanent malfunction
27600	01	244549	10/26/2005	254605	10/20/2005	10/26/2005	N/A	67,792	99999977U W	HANDLING CHARGE UCPP \$50.00 PER REPAIR VISIT
27600	01	244540	10/26/2005	254605	10/20/2005	10/26/2005	N/A	67,792	11120332U W	CYLINDER HEAD-DISTORTED
27600	01	215469	08/10/2005	250788	08/01/2005	08/10/2005	N/A	63,623	99999977U W	HANDLING CHARGE UCPP \$50.00 PER REPAIR VISIT
27600	01	215460	08/10/2005	250788	08/01/2005	08/10/2005	N/A	63,623	11729476U W	E38 E39 E52 E53 M62/TU S62 SEKUNDAERLUFTKANAELE VERKOKT (FC 80/81)

Center ID	Location ID	Claim Number	Claim Date	Repair Order #	Repair Order Date	Repair Entry Date	Davis #	Mileage	Defect Code	Description	
27600	01	178749	04/20/2005	244772	04/14/2005	04/20/2005	N/A	56,128	99999977U W	HANDLING CHARGE UCPP	\$50.00 PER REPAIR VISIT
27600	01	178740	04/20/2005	244772	04/14/2005	04/20/2005	N/A	56,128	12610015U W	ENG OIL LVL SENSOR-PERM MALFUNCT	
27600	01	155960	02/05/2005	240497	02/01/2005	02/05/2005	N/A	51,175	1214151200	Component, DME control unit permanent failure	
27600	01	76960	07/10/2004	229930	07/08/2004	07/10/2004	N/A	38,333	51331239U W	WINDOW REGULATOR, FRONT UNPLEASANT NOISES	
27600	01	76969	01/01/1900	0	07/08/2004	01/01/1900	N/A	38,333	99999977U W	HANDLING CHARGE UCPP	\$50.00 PER REPAIR VISIT
27600	01	27500	02/03/2004	220606	01/23/2004	02/03/2004	N/A	36,352	62141112CR	\\ \\ NO LOCAL LANG DESCRIPTION FOR THIS DEFECT COD	
27600	01	776300	00/00/0000	180837	09/27/2001	00/00/0000	N/A	15,026	85990091MP	OIL SERVICE(MP)AFTER THE 1ST	
27600	01	671370	00/00/0000	163708	06/13/2000	00/00/0000	N/A	1,152	0061420100	SIB #63-02-00 RECALL 00V-048 BRAKE SWITCH	
27600	01	671360	00/00/0000	163708	06/13/2000	00/00/0000	N/A	1,152	0012410100	SIB #12-24-99 CHECK ENGINE LIGHT E39 M5 PRODUCED UP TO 02/2000	
27600	01	671351	00/00/0000	163708	06/13/2000	00/00/0000	N/A	1,152	85990088MP	1200 MI SERV -M5,Z8,S54B32 M3	
27600	01	671350	00/00/0000	163708	06/13/2000	00/00/0000	N/A	1,152	85990088MP	1200 MI SERV -M5,Z8,S54B32 M3	
96311	01	72530	00/00/0000	104947	11/04/1999	00/00/0000	N/A	1	1214169800	Data status, DME control unit not satisfactory	